

Virginia Department of Historic Resources PIF Resource Information Sheet

This information sheet is designed to provide the Virginia Department of Historic Resources with the necessary data to be able to evaluate the significance of the property for possible listing in the Virginia Landmarks Register and the National Register of Historic Places. This is not a formal nomination, but a necessary step in determining whether or not the property could be considered eligible for listing. Please take the time to fill in as many fields as possible. A greater number of completed fields will result in a more timely and accurate assessment. Staff assistance is available to answer any questions you have in regards to this form.

General Property Information	For Staff Use Only DHR ID #: <u>042-0189</u>
Property Name(s): <u>Quietude</u>	
Property Date(s): <u>1820</u> <input checked="" type="checkbox"/> Circa <input type="checkbox"/> Pre <input type="checkbox"/> Post	Open to Public? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> Limited <input type="checkbox"/> No
Property Address: <u>7351 McClellan Rd</u> City: <u>Mechanicsville</u> Zip: <u>23111</u>	
County or Ind. City: <u>Hanover</u> USGS Quad(s):	

Physical Character of General Surroundings	
Acreage: <u>13.64</u>	Setting (choose one): <input type="checkbox"/> Urban <input type="checkbox"/> Town <input type="checkbox"/> Village <input type="checkbox"/> Suburban <input checked="" type="checkbox"/> Rural <input type="checkbox"/> Transportation Corridor
Site Description Notes/Notable Landscape Features: The house is set a distance off the main road with pecan and walnut trees lining the gravel driveway. There are many old cedar, katalpa, poplar, and boxwoods on the property. There is a large open field which has been farmed to the present day and a forested area behind the house. The property originally was substantially larger as indicated by the county's records.	
Secondary Resource Description (Briefly describe any other structures (or archaeological sites) that may contribute to the significance of the property): To the South of the main house is the old kitchen. There is an old well, smokehouse, log cabin, and ruins of a brick bread oven and another similar structure. All these, are believed to date to the early 19th century. We have found older colonial era artifacts in the forest behind the house, possibly indicating an older building site behind the present day house.	
Ownership Category: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public-Local <input type="checkbox"/> Public-State <input type="checkbox"/> Public-Federal	

Individual Resource Information	
What was the historical use of this resource? Examples include: Dwelling, Grist Mill, Bridge, Store, Tobacco Barn, etc... <u>plantation house</u>	
What is the current use? (if other than the historical use)	Private residence. We are working to gain all needed approvals to open the gardens and house as a historical site to the public and to build a Hindu Church on the property.
Architectural style or elements of styles:	<u>Colonial Georgian style 1 and 1/2 story raised cottage</u>
Architect, builder, or original owner:	<u>possibly Edmund Waide</u>
# of stories <u>3</u> Condition: <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Poor <input type="checkbox"/> Ruins <input type="checkbox"/> Rebuilt <input type="checkbox"/> Renovated	
Are there any known threats to this property? <u>Overgrowth, termites and deterioration, which we are currently working to remedy</u>	

Resource Component Information

Please answer the following questions regarding the individual components of the resource. If the component does not exist, answer "n/a." If you feel uncomfortable in answering the question, please leave the space blank. Photographs of the features can also help our staff identify specific feature components. Usually, priority is given to describing features on the primary (front) facade of the structure.

Foundation: Describe the foundation that supports the structure. Examples include piers, continuous brick, poured concrete.

Brick 3 course and 5 course American bond

Structure: Describe the primary structural component of the resource. Include primary material used. Examples include log, frame (sawn lumber), and brick. Also include the treatment, such as a particular brick bond or type of framing, if known.

sawn timber frame

Walls: Describe the exterior wall covering such as beaded weatherboard or asbestos shingles.

beaded wooden weatherboard

Windows: Describe the number, material, and form of the primary windows. This includes the number of panes per sash, what the sashes are made of, and how the sashes operate (are they hinged or do they slide vertically) Have the windows been replaced? The facade has 9 windows. The main floor has 4 nine over nine light, double hung wooden sash windows with shutters. The English basement and gabled dormer windows are six over six light double hung wooden sash windows.

Porch: Briefly describe the primary (front) porch. List the primary material, shape of the porch roof, and other defining details. One story, one bay porch. Chamfered posts with lambs tongue stops support the gabled roof. The porch is wooden on a brick foundation.

It appears to be a later addition to the house.

Roof: Describe the roof, listing the shape and the covering material.

The roof is gabled with 5 gabled dormers protruding and is covered in dimensional asphalt shingles.

Chimney(s): List the number of chimneys and the materials used. Include the brick bond pattern if possible.

There are two exterior chimneys both laid in five course American bond. Two pents flank the South chimney, which appear to be late 19th or early 20th century additions.

Architectural Description of Individual Resource: *(Please describe architectural patterns, types, features, additions, remodelings, or other alterations. A sketch of the current floor plan would be appreciated.)*

In addition to the aforementioned pents adjacent to the chimney, there is one rear pent added in the late 19th or early 20th century and a two story addition containing a bathroom added around the 1940's constructed from cinder blocks and covered in vinyl siding. A ground level brick gutter surrounds the house with some later additions of concrete surrounding the bricks. Three old lightning rods sit on top of the roof. The detached kitchen stands on a brick foundation laid in 3 course American bond which encloses a root cellar. Above the kitchen is a gabled storage area. The kitchen has an addition dating to the 1940's or 1950's. There are several other 20th century structures on the property, in addition to the aforementioned 19th century structures.

We believe the southern half of the main house was constructed around 1820 and the Northern portion around 1850. Many 19th century features ~~remain~~ remain in the house. Historians have dated the house from building styles and ~~technique~~ technique prevalent at these dates and occurring in the house.

Significance Statement: Briefly note any significant events, personages, and/or families associated with the property. (Detailed family genealogies are not necessary.) Please list all sources of information. It is not necessary to attach lengthy articles or genealogies to this form. Normally, only information contained on this form will be posted for consideration by the State Review Board.

Quietude exemplifies typical rural Virginia plantation. The kitchen, well, and bread oven in particular offer a glimpse into the life and work of a 19th century planters. It was possibly built by Edmund Waide who married Welthy Ann Atkinson of King William County in January of 1838. The estate was inherited by his son James D. Waide who was an educator and taught at a school that was located at the site of what is now Camp Hanover. James Waide served as a Captain during the Civil War. We have recovered several civil war artifacts on the property which indicate the Northern troops may have occupied the house during the Civil War. We are working to excavate other artifacts and historical documents to help us to reveal more of the story of the site.

locate

Legal Owner(s) of the Property (For more than one owner, please use a separate sheet.)

Mr. Mrs. Dr.
 Miss Ms. Hon. Kevin Decamp
 (Name)

7351 McClellan Rd (Address) Mechanicsville VA (Firm) 23111 (City) (State) (Zip Code)

kevindecamp@gmail.com (Email Address) 631 742 8629 (Daytime telephone including area code)

Owner's Signature: *Kevin Decamp* Date: 4/12/2016
 •• Signature required for processing all applications. ••

In the event of corporate ownership you must provide the name and title of the appropriate contact person.

Contact person: _____

Daytime Telephone: ()

Applicant Information (Individual completing form if other than legal owner of property)

Mr. Mrs. Dr.
 Miss Ms. Hon. Gananath Giri
 (Name)

7351 McClellan Rd (Address) Mechanicsville VA (Firm) 23111 (City) (State) (Zip Code)

somamatha@gmail.com (Email Address) 757 620 1468 (Daytime telephone including area code)

Applicant's Signature: *Gananathamitaramanda* Date: 4/12/2016

Notification

In some circumstances, it may be necessary for DHR to confer with or notify local officials of proposed listings of properties within their jurisdiction. In the following space, please provide the contact information for the local County Administrator or City Manager.

Mr. Mrs. Dr.
 Miss Ms. Hon. Rhu Harris County Administrator
 (Name) (Position)

Hanover PO Box 470 7497 County Complex Rd (Locality) (Address)

Hanover VA 23069 804 365 6005 (City) (State) (Zip Code) (Daytime telephone including area code)

Please use the following space to explain why you are seeking an evaluation of this property.
 To help honor and preserve the ~~unique place~~ unique place of this historical site for future generations.

Would you be interested in the State and/or the Federal Rehabilitation Tax Credits? Yes No *Maybe*

Would you be interested in the easement program? Yes No

042-0189 2016 PIF

Not to scale




- A- Quietude (Main House)
- B- Old kitchen
- C- Old Well
- D- Bread oven
- E- Brick ruins
- F- Mounting Block
- G- Smoke House
- H- 20th C. Pole Barn
- I- 20th C. Cottage
- J- ~~Pr~~ Privy
- K- Log Cabin
- L- Archeological site with colonial artifacts

McClellan Rd Rte. 628


Second Floor



First Floor



English Basement



042-0109 2016 711

Quietude Floor Plan